

Safety Recall Quarterly Report Information

Report Date: January 10, 2000

Calendar Quarter: 1

Safety Recall Quarterly Report from October 1999 through December 1999

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: Dana Aluminum Steering Driveline

1. NHTSA Safety Recall Campaign No. 99V-303

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW4

2. (a) The date notification to purchasers began: 12/9/99

(b) The date notification to purchasers was completed: 12/2999

3. The total number of items¹ involved: 3662

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 348

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 191

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable: 190

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____

¹ Items shall refer to the vehicles, parts or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: April 18, 2000

Calendar Quarter: 2

Safety Recall Quarterly Report from January 2000 through March 2000

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: Dana Aluminum Steering Driveline

1. NHTSA Safety Recall Campaign No. 99V-303

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW4

2. (a) The date notification to purchasers began: 12/9/99

(b) The date notification to purchasers was completed: 12/2999

3. The total number of items¹ involved: 3662

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 829

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 973

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable: 190

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.

Safety Recall Quarterly Report Information

Report Date: July 17, 2000

Calendar Quarter: 3

Safety Recall Quarterly Report from April 2000 through June 2000

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: Dana Aluminum Steering Driveline

1. NHTSA Safety Recall Campaign No. 99V-303

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: 99KW4

2. (a) The date notification to purchasers began: 12/9/99

(b) The date notification to purchasers was completed: 12/2999

3. The total number of items¹ involved: 3662

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale:

1027

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 1374

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable: 0

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____

Safety Recall Quarterly Report Information

Report Date: October 13, 2000

Calendar Quarter: 4

Safety Recall Quarterly Report from July 2000 through September 2000

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: Dana Aluminum Steering Driveline

1. NHTSA Safety Recall Campaign No. 99V-303

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code:

99KW4

2. (a) The date notification to purchasers began: 12/9/99

(b) The date notification to purchasers was completed: 12/9/99

3. The total number of items¹ involved: 3662

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 1056

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 1491

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable: 0

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or items involved in the safety recall on which you are reporting.
dana_driveline.doc

Safety Recall Quarterly Report Information

Report Date: January 16, 2001

Calendar Quarter: 5

Safety Recall Quarterly Report from October 2000 through December 2000

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: Dana Aluminum Steering Driveline

1. NHTSA Safety Recall Campaign No. 99V-303

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code:

99KW4

2. (a) The date notification to purchasers began: 12/9/99

(b) The date notification to purchasers was completed: 12/9/99

3. The total number of items¹ involved: 3662

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 1062

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 1530

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____

¹ Items shall refer to the vehicles, items or equipment or tires involved in the safety recall on which you are reporting.
99kw4 dana driveline.doc

Safety Recall Quarterly Report Information

Report Date: April 20, 2001

Calendar Quarter: 6

Safety Recall Quarterly Report from January 2001 through March 2001

Manufacturer: PACCAR Inc (Kenworth)

Report Author: Kenneth R. Brownstein Phone (425) 468-7356

Recall Subject: Dana Aluminum Steering Driveline

1. NHTSA Safety Recall Campaign No. 99V-303

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code:

99KW4

2. (a) The date notification to purchasers began: 12/9/99

(b) The date notification to purchasers was completed: 12/9/99

3. The total number of items¹ involved: 3662

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 1067

Includes (a) the total number of items returned from manufacturer, distributor, dealer or retailer inventory or (b) otherwise remedied prior to sale to consumers.

Do not include this number in 4(a) or 4(b).

4. (a) Total number inspected & remedied: 1567

Total number of items which were inspected and/or otherwise repaired or remedied (cumulative).

(b) Total number inspected & NOT REQUIRING REMEDY: 0

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable

Total number exported: 0

Total number stolen: 0

Total number scrapped: 0

Total number unable to notify: 0

Total number otherwise unreachable: 0

Describe other: _____